

## COMMUNITY DEVELOPMENT DEPARTMENT BUILDING DIVISION

200 S. Spruce Street • PO Box 20,000-5005 • Grand Junction, Colorado • 81502 Telephone: 970.244.1631 • www.mesacounty.us/building

## **Policy on Blower Door and Duct Testing**

The 2021 International Energy Conservation Code requires testing of the air leakage rate per R402.4.1.2 and duct leakage per R403.3.6. Mesa County will not require an approved third party to perform blower door or duct testing (when applicable). If results are found to be inaccurate or false, the person/company listed on the test results is subject to having their ability to perform tests revoked. A written report of the results of the test shall be provided. The report shall be a computer-generated document with the person/company who conducted the test. The report of the results must be signed by the party conducting the test and provided on site for inspection.